A

B

S.J.C. COMMUNITY
JAN 15 2016

Photo
Taken by
Jon Rumstad
1/16/11

A. Emergency/temporary
Repair
Bank
Undercutting

B

02.09.2011 16:23

Contractor
Photos:
B. Wiscomb

Showing 2 of 3
areas were
slope/beach
stabilized
(dirt on slope)

Photo by
Contractor
B. Wiscomb

Taken
1/26 - 2/3/11

Contracts
B. Wiscomb
Photo Taken
in period 1/26 - 2/3/11

M.O.E. COMMENTS
JAN 15 2013

Photos:
J. Runstad
1/16/11

A. Erosion
Sloughing

B. Erosion
Sloughing
(Same site)